

Completed jobs during July and August 2025

Alvington

FAL19 A new pedestrian footbridge was installed by my contractor on 18th July, near to Court Farm. This replaced the broken one that we had known about for the last two years but we had been unable to access previously due to the wet ground conditions.

Enquiry Refs – 22056418 / 11429113 / 11417994 / 11401034 (All Resolved)



Aylburton

FAY36 A new pedestrian footbridge adjacent to the recreation ground was installed by my contractor on 25th June. However, due to concerns about horses gaining access to the bridge, we installed some additional firmer wire mesh to the sides of the bridge on 11th July. Enquiry Refs – 11488981 (Resolved) / 11488962 (Resolved)



Awre & Blakeney

DAW13 Inspected this Public Footpath at Oaklands Park on 26th June following complaints that it was blocked by an electric fence. However, upon inspection found that an electric fence was no longer present and neither was any livestock in the field either.

Enquiry Ref – 22080798 (Resolved)

DAW46 On 7th July my contractor cleared this Public Footpath north of Blakeney Recreation Ground that was previously impassable due to Himalayan Balsam and other vegetation.

Enquiry Ref – 22079795 (Resolved)

DAW55 Inspected this Public Footpath between the A48 and Swan Lane on 19th August and found where it was blocked by a fallen tree and vegetation as reported. I will task my contractor to clear this as soon as possible.

Enquiry Ref – 22084174 (Work Required)

DAW59 / Severn Way West It was reported that this Public Footpath near to Hall Farm was blocked in a couple of locations. My contractor was tasked to clear these and this was completed on 4th and 7th July. Thanks were received from the customer who had reported it.

Enquiry Ref – 11488908 (Resolved)

DAW73 Following a previous discussion with the landowner concerning this blocked Public Footpath at Etloe, I reinspected it on 4th July. I found that where it had previously been blocked by brambles it had now been cleared. My contractor was also tasked to clear a stile of vegetation and low hanging branches that were blocking the route on neighbouring land and this was completed on 8th July, as well as making a clearer line through the maize crop than had been provided by the farmer. I also visited site on 2nd July and cleared the field gate on the Etloe Road of overgrown brambles that had completely blocked the access at that point. Also installed seven new waymark discs on the route to indicate its position.

Enquiry Ref – 22080103 (Resolved) / 22080102 (Resolved)



DAW72 It was noted that the signpost had gone missing from the start / end of this Public Footpath on the Etloe Road. My contractor was tasked to install a new one and this was completed on 2nd July. I also visited site later the same day and installed a new pointer. Whilst there a local resident pulled up and queried the signpost, unaware a Public Footpath existed there!

DAW82 On 2nd July my contractor cleared the signpost on the Etloe Road end of this Public Footpath that had previously been obstructed by vegetation. As this was now the alternative route for the Severn Way West route from DAW84, it was essential that this route was easy to find.

DAW87 / Severn Way West It was reported that this Public Footpath was blocked by overgrown brambles north of Little Hagloe and close to the railway line. I inspected this on 4th July with my contractor, found the location where it was blocked and it was cleared the same day.
Enquiry Ref – 22075820 (Resolved)

DAW87 / Severn Way West Another section of this Public Footpath just north of Poulton Court Farm was reported as blocked by overgrown brambles and fallen trees. My contractor was instructed to clear this and I attended site with him on 19th August to get it cleared as this had proven impossible on his previous visit due to the over attentive and inquisitive nature of a herd of frisky cattle. On this occasion my presence prevented the cattle from getting in his way and the obstructions were successfully cleared.
Enquiry Ref – 22057031 (Resolved)



DAW93 My contractor installed a new metal kissing gate on this Public Footpath near Awre village hall on 10th July, replacing a very broken wooden stile. This was made possible thanks to a grant from the local County Councillor and permission from the landowner.

DAW95 / Severn Way West My contractor was tasked to clear the overgrown brambles and vegetation from this Public Footpath which runs north and riverside from Woodend Lane to the junction of DAW87 and DAW112. This was completed on 11th August 2025.

DAW99 Responded to customer enquiry on 7th July with regards to broken pointers on the signpost close to Awre church. Notified them that there were a few known issues with both DAW98 and DAW99 where in effect they were both dead end paths. I had decided not to take any further action because I didn't have the resources (particularly the funding) to clear a 180-metre section of bridleway which went nowhere. In addition, very recently, the Wetlands and Wildfowl Trust had now purchased this land to turn into a saltmarsh. Therefore, it was expected that these two Public Rights of Way would shortly be diverted onto higher land at the edge of the nature reserve / saltmarsh. This plan backed up my earlier decision not to incur the great expense required to clear the PROW which would probably not be there in a couple of years' time.

Enquiry Ref – 11484891 (Resolved)

DAW112 / Severn Way West It was reported that this Public Footpath was blocked by overgrown reeds and brambles. I therefore instructed my contractor to clear this and this was undertaken on 14th July.

Enquiry Ref – 22081160 (Resolved)

Blaisdon

DBL28 A new pedestrian bridge was installed by my contractor on this Public Footpath near to Gaulett Farm on 2nd July. This replaced the broken and impassable one that we had not being able to access for the last two years, due to the wet ground conditions.

Enquiry Ref – 22036541 (Resolved)



Churcham

DCH76 The customer had previously requested copies of the Definitive maps for this Public Footpath and others near to Churcham church. I visited the customer and explained the positions of the footpaths, which varied to that being walked on the ground! A further discussion took place in June and additional historic maps were supplied to the customer. As nothing further has since been heard then I'm assuming that the customer is now satisfied with the information supplied.
Enquiry Ref – 22064443 (Resolved)

Cinderford

DCF4 It was reported that this Public Footpath between Flaxley Street and Woodside Avenue had overhanging vegetation from the sides of the path. My contractor was instructed to clear this and this was completed on 14th July.
Enquiry Refs – 11489367 (Resolved) / 11488456 (Resolved)

Coleford

RCO6 It was reported that the wooden stile close to Poolway Farm was broken and become dangerous as the step was rather high. I attended site on 19th August and established that the bottom stile step which was hidden in the vegetation was broken and almost non-existent. Whilst there I spoke with the landowner and agreed that my contractor could replace the bottom step with a new one and this was completed on 20th August.
Enquiry Ref – 22075883 (Resolved)

RCO9 Installed three 'no cycling' waymark discs on the Scowles road end of this Public Footpath.
Enquiry Ref – Email (Resolved)

RCO17 It was reported that the stile step was broken on the wooden stile close to Poolway Farm and at the junction of RCO6. I visited site on 19th August, established the extent of the problem and then my contractor replaced the broken / rotted stile riser on 20th August.
Enquiry Ref – 22075885 (Resolved)

RCO21 It was reported by one of my volunteers that this diagonal Public Footpath between Coalway Road and Bells Golf Course was almost impassable due to overgrown vegetation. I therefore instructed my contractor to clear this and this was completed on 24th July.
Enquiry Ref – 22082554 (Resolved)

RCO22 It was reported by one of my volunteers that this Public Footpath between Coalway Road and Bells Golf Course was almost impassable due to overgrown vegetation. I therefore instructed my contractor to clear this and this was completed on 24th July.
Enquiry Ref – 22082556 (Resolved)

RCO25 It was reported that this Public Footpath between Rock and Pingry Lanes was not only obstructed by overgrown vegetation but also a wheat crop at mid distance. I therefore instructed my contractor to clear it with the robotic flail and this was completed on 4th July.
Enquiry Ref – 22081341 / 22079328 / 22076816 / 22058218 (All Resolved)

RCO27 It was reported by one of my volunteers that this Public Footpath between Newland Street and the Rec Ground was almost impassable due to overgrown vegetation. I therefore instructed my contractor to clear this and this was completed on 22nd July.
Enquiry Ref – 22079338 (Resolved)

RCO28 It was reported by one of my volunteers that this Public Footpath between Newland Street and the Rec Ground was almost impassable due to overgrown vegetation. I therefore instructed my contractor to clear this and this was completed on 22nd July.
Enquiry Ref – 22079501 (Resolved)

Drybrook

DDB7 Inspected this Public Footpath next to the property 'Netherleigh' on 9th July and noted the silt and rubble that had piled up on the edge of the footpath next to the wall. My contractor will be tasked to clear this as soon as possible.
Enquiry Ref – 11486964 (Work Required)

DDB37 Inspected this Public Footpath next to the property 'Rogelyn' on 17th July. Found the reported overgrown vegetation that was causing the path to be impassable, and I will task my contractor to clear this in the autumn.
Enquiry Refs – 22080829 / 11377878 (Work Required)

English Bicknor

REB18 A few trees had been reported as fallen across the line of this Public Footpath. Following discussions with Parish Councillors and a couple of the adjacent landowners, my contractor was instructed to clear them and this was completed on 8th July.
Enquiry Ref – 11484234 (Resolved)

Huntley

DHU44 Inspected this Public Bridleway on 17th July and noted the reported uneven tarmac surface. As it currently stands then the bridleway is perfectly usable for horse riders, but I can understand the issues presented to the property owners who drive their vehicles up and down the bridleway. I will see if funding can be identified to solve the worst of the issues, but I need to remind people that the authority is only obliged to maintain the bridleway to a standard suitable for horse riders and cyclists and damaged caused by private vehicular use should be the responsibility of the property owners to repair the damage caused.
Enquiry Ref – 11489625 (Action Required)

DHU45 Inspected this Public Footpath just off the A40 at Birdwood on 16th July, cleared several brambles blocking the path, installed new waymark discs and replaced the broken pointer on the signpost roadside.
Enquiry Refs – 22079103 (Resolved) / 22077952 (Resolved)

DHU54 It was reported that this Public Footpath just off the A4136 at Little London was blocked by overgrown vegetation. When I inspected on 16th July, I found the steps near to the main road were impassable and fallen tree branches were obstructing the route near to the footbridge. I therefore instructed my contractor to clear these and this was completed on 17th July.

Enquiry Refs – 22080868 / 22079101 / 11489828 (All Resolved)

Littledean

NOT PROW A new aggregate path was installed by my contractor on 30th July, leading from the Slad to the phone box.

Enquiry Ref – 11488412 (Resolved)

Longhope

DLH4 A new pedestrian footbridge was installed by my contractor on this Public Footpath just off Barrel Lane on 24th July. The previous one had completely collapsed, and access had not been possible until now due to the previously wet ground conditions.

Enquiry Ref – 22056185 (Resolved)



DLH9 / Glos & Wysis Way Inspected this Public Bridleway on 24th July and noted the continued presence of kissing gates. I have contacted the National Trust ranger responsible for May Hill and am awaiting his call back so that we can move forward with replacing the kissing gates with proper bridle gates whilst maintaining a secure area for the cattle on their land.

Enquiry Refs – 22055708 / 22055706 / 22055704 (Ongoing)

- DLH17 / Glos Way It was reported to us that this Public Footpath between the A40 Nags Head Cottages and Barrel Lane had become overgrown with vegetation. My contractor was instructed to clear this and this was completed on 13th August.
Enquiry Ref – 22079278 (Resolved)
- DLH23 I contacted the customer on her mobile on 24th June and provided her with the details and prices of kissing gates and stiles. She was going to speak to her husband about what they were going to do next to replace the broken stiles on this Public Footpath. However, as no response has yet been forthcoming, I have now closed this issue as 'Enquiry Resolved'.
Enquiry Ref – 11488864 (Resolved)
- DLH26 / Glos Way Reinspected this Public Footpath on 5th August where it crosses the stream to the private driveway to the property Hill View, and where the bridge has been damaged by a fallen oak tree. My contractor has been instructed to remove the fallen tree and repair the stone abutment to this pedestrian bridge as soon as possible.
Enquiry Ref – 11471740 (Work Instructed)
- DLH28 Inspected Public Footpath on 17th July and found the reported broken gate post. I now need to identify the landowner and establish what they are planning to do to replace it.
Enquiry Ref – 22058093 (Action Required)
- DLH33 Inspected Public Footpath on 17th July and met with landowner at Chessgrove Farm. It was reported that there was an issue with frisky cattle, but whilst I was there, they wouldn't come anywhere near us even when we attempted to get nearer them.
Enquiry Ref – 22074430 (Resolved)
- DLH38 / Glos Way My contractor installed a new signpost and pointer on this Public Footpath leading from the A4136 towards Whitmore Farm on 21st July. This replaced the previous one which had been damaged beyond repair following a road accident.
- DLH61A On 21st July, my contractor repaired the damaged surface of the diverted route of this Public Footpath at Blakemore Farm and installed a new drain to prevent further damage. The northern end of the diverted route also had a new aggregate surface installed by my contractor between 19th – 22nd August, which now leaves a middle section to be improved before the proposed diverted route can be certified.
- DLH67 It was reported that this Public Bridleway near to Blakemore Farm and adjacent to the property 'Lonehead' was overgrown and an inspection with my contractor a couple of months previous found that to be the case. My contractor was tasked to clear this and this was completed on 21st July.
Enquiry Ref – 22063721 (Resolved)

DLH71 I inspected this Public Footpath near to Chapel Lane and in accordance with the photos I had been sent, the footpath was not closed as claimed but it was evident that the contractors working on the adjacent property had been repairing the wall on the edge of the footpath. In view of this I closed the issue as 'Enquiry Resolved'.
Enquiry Ref – 11486060 (Resolved)

DLH101 On 9th July I cleared the signpost of vegetation that had been obstructing it at the start / end of this Public Footpath adjacent to the A4136.

Lydbrook

RLY1 It was reported that this Public Footpath was blocked by overgrown vegetation. As this is one of the paths on the cyclical maintenance agreement, my contractor went and cleared it the same day. I also visited site on 30th July and cleared back the vegetation from the start / end of this Public Footpath where it emerges onto the Lydbrook Road so as to make access / egress safer for walkers.
Enquiry Ref – 22081305 (Resolved)

RLY11 It was reported that this Public Footpath was obstructed by overgrown vegetation. I tasked my contractor to clear this and this was completed on 14th July.
Enquiry Ref – 22080709 (Resolved)

RLY12 It was reported that this Public Footpath was obstructed by overgrown vegetation. I tasked my contractor to clear this and this was completed on 14th July.
Enquiry Ref – 22080710 (Resolved)

RLY33 Several people had reported issues with the grass surface on this Public Bridleway in the Pludds being flattened due to vehicles turning at the entrance to it. When I inspected on 29th July, I found that the surface had not changed at all since my previous inspection on 4th June.
Enquiry Refs – 22082883 / 22082810 / 22082728 (All Resolved)

RLY44 On 1st August installed signage on this closed Public Footpath at Stowfield Bridge advising walkers of the alternative route as supplied by Wye Valley National Landscapes.

Lydney

FLY14A It was reported that the signpost at the start / end of this Public Footpath on Grove Road had fallen over as the base had rusted through. My contractor was tasked to install a new signpost and this was completed on 2nd July. I also visited site later the same day and installed a new pointer.
Enquiry Ref – 22072999 (Resolved)

FLY28 It was reported by one of my volunteers in Lydney that this Public Footpath between Highfield Road and Centurion Road was impassable in the spring due to thick mud at mid-distance. I inspected the footpath on 25th June and found the problems that had been reported. I instructed my contractor to lay a new aggregate path and clear back the vegetation and this was completed on 3rd and 4th July. See photos below.
Enquiry Ref – 22077488 / 11489759 / 11457901 (All Resolved)



FLY36 It was reported that this Public Footpath was obstructed by overgrown vegetation, but when I inspected it on 10th July, I could find no such issues.
Enquiry Ref – 22080414 (Resolved)

FLY44 Inspected this Public Footpath near Cliff Farm on 19th August and noted the recent surface improvements that had been carried out by my contractor following permission from the landowner. The path had been cleared of vegetation, widened and enabled walkers safer access away from the steep cliff edge.
Enquiry Ref – 22033600 (Resolved)

FLY70 It had been reported that the footbridge on this Public Footpath over the Plummers Brook in Tingley Wood had been washed away and when I inspected back in March, I found that to be the case. I therefore instructed my contractor to replace it with a new one and following discussions with the landowner access was granted through his fields. The new 1.2-metre-wide bridge was installed on 17th July.

Enquiry Ref – 22072784 (Resolved)



FLY82 Inspected this Public Footpath between The Hawthorns and Highfield Road on 10th July and noted the overgrown hedge that was now obstructing the steps on this small section. My contractor will be tasked to clear this as soon as possible in the autumn at the end of the bird nesting season.

Enquiry Ref – Email (Work Required)

FLY88 It was reported to us that the wooden stile near to the A48 end of this Public Footpath next to the cemetery had broken steps. The decision was taken to replace the stile with a metal kissing gate, and this was installed by my contractor on 1st August.

Enquiry Ref – 11486187 (Resolved)

FLY91 The signpost roadside at Highfield Road was up righted having been knocked over.

Enquiry Ref – 22057650 (Resolved)

Mitcheldean

DMD27 / Wysis Way It had been reported to us that this Public Footpath which runs between the town of Mitcheldean and the Wilderness Study Centre had become overgrown with vegetation and almost impassable behind properties at Wintles Close. My contractor was instructed to clear this and this was completed on 14th August 2025.

Enquiry Ref – 11492120 (Resolved)

Newland

- RNE1 This Public Footpath which runs riverside from the A466 at Redbrook was reported as overgrown from Himalayan balsam and other vegetation. My contractor was tasked to clear this and this was completed on 23rd July 2025.
Enquiry Ref – 22082815 (Resolved)
- RNE32 It was reported that the section of this Public Footpath near to and behind the Noble Foods Factory between Clearwell and Coleford had become almost impassable due to overgrown vegetation. My contractor was tasked to clear this and this was completed on 6th August.
Enquiry Refs – 22083642 (Resolved) / 2203077 (Resolved)
- RNE52 From studying the photograph supplied with this report it was obvious that a line has been cleared through the crop by the farmer as opposed to the claim that it had been created by walkers. There was no further action required on this one, especially as the customer had chosen to be anonymous.
Enquiry Ref – 22081934 (Resolved)
- RNE57 It was reported that the section of this Public Footpath south of Platwell Farm and Platwell House had become almost impassable due to overgrown vegetation. My contractor was tasked to clear this and this was completed on 6th August.
Enquiry Refs – 22082894 (Resolved) / 2203225 (Resolved)
- RNE58 It was reported to us that the wooden stile on this Public Footpath opposite the Orepool Inn had become overgrown with brambles. My contractor was tasked to clear this and this was completed on 6th August.
Enquiry Ref – 22082856 (Resolved)
- RNE59 It was reported that this Public Footpath next to the cemetery at Clearwell was obstructed by overgrown vegetation. I tasked my contractor to clear this and this was completed on 23rd July.
Enquiry Ref – 22082626 / 22082625 / 22082624 / 22082623 / 22082262 (All Resolved)

Ruardean

- DRD19 It was reported by an anonymous customer that a few gates in different locations were padlocked shut. However, when I inspected them on 9th July, I found that they were either on openable clasp locks or simply opened on the catch.
Enquiry Refs – 22081197 / 22081187 / 22081186 (All Resolved)

Ruspidge & Soudley

DRP5 It was first reported on 9th August 2025 that this Public Footpath between Ruspidge Road and Edmunds Way was overgrown with vegetation. It was also claimed that this had previously been reported months ago, but a check of the database could not locate any further reports from this year. I visited site on 19th August and noted that the Public Footpath was perfectly passable and whilst long grass was to both sides of the footpath it would better be described as untidy. However, I tasked my contractor to clear this grass and this was completed on 20th August.
Enquiry Ref – 22084075 (Resolved)

St.Briavels

FSB46A It was reported that this Public Footpath was blocked by overgrown vegetation. As this is one of the paths on the cyclical maintenance agreement, my contractor went and cleared it the same day.
Enquiry Ref – 22081495 (Resolved)

FSB118 / Glos Way It was reported earlier in the year that this Public Footpath near to Rodmore Grove and Clanna Woods was basically impassable due to the deep rutted ground from forestry operations. An inspection by a fellow PROW officer and myself found that to be the case. However, when I returned on 17th July even though the ground was still quite uneven, I found that a walkable path had been created and thanks to the recent dry weather the ground conditions had hardened well from the soft mire that was there previously. So much so that I am happy to close this issue as Enquiry Resolved.
Enquiry Ref – 22069154 (Resolved)

Staunton near Coleford

RST12 Inspected Public Footpath on 17th July and located the reported overhanging branches. I will task my contractor to clear these in the autumn, as soon as the bird nesting season is over.
Enquiry Ref – 22082632 (Work Required)

Tidenham

FTM15 It was reported that the signpost at the start / end of this Public Footpath on Rosemary Lane had fallen over as the base had rusted through. My contractor was tasked to install a new signpost and this was completed on 2nd July, as well as reattaching the existing unbroken pointers for FTM11 and FTM15.
Enquiry Ref – 22078738 (Resolved)

FTM44 / 45 / 46 Inspected these Public Footpaths on 30th July in connection with my response to planning application P0726/25/FUL which was sent on 6th August. As per my original response to P1411/21/FUL, I found that the routes on the ground did not entirely match up with those on the Definitive map, including a blockage by a farm building on the line of FTM46. I highlighted to the planning officer that it was imperative that the applicant applied for a diversion of the Public Footpath as part of this latest planning application and as was previously requested but seemingly ignored.
Enquiry Ref – Email (Resolved)

FTM71 It was reported that the two kissing gates on this Public Footpath near to Bishton Farm were impassable due to fallen branches across the one and overgrown hedgerow at the other. I visited site with my contractor on 24th July where they were both cleared and access was possible once more.

Enquiry Refs – 22082023 (Resolved) / 22082022 (Resolved)

FTM73 It was reported that whilst not impassable, the kissing gate on this Public Footpath north of Bishton Farm was obstructed by overhanging dense bramble bushes. When I inspected on 24th July, I found this to be the case, and my contractor cleared them back on 29th July.

Enquiry Ref – 22082021 (Resolved)

FTM75 / Glos Way It was reported that this Public Footpath to the rear of Bishton Farm was almost impassable due to overgrown vegetation. I tasked my contractor to clear this and this was completed on 24th July.

Enquiry Ref – 22082020 (Resolved)

FTM82 Inspected this Public Footpath on 24th July next to Piermont Drive but could not locate any issues with barbed wire near to the footpath as reported by the customer.

Enquiry Ref – 22075726 (Resolved)

FTM87 It was reported that this Public Footpath at Buttington Causeway had become overgrown and impassable. My contractor was instructed to clear this and this was completed on 30th July, as well as clearing the two drainage pipes that run under the causeway.

Enquiry Ref – 22083293 (Resolved) / 11489616 (Resolved)

FTM107 / Offa's Dyke Path Inspected this Public Footpath on 22nd July 2025 with one of our volunteers and the Chief Executive of the Offa's Dyke Association. Reviewed how recent clearances of the vegetation had been successful and agreed on a plan for future works.

FTM113 / Offa's Dyke Path Inspected this Public Footpath on 9th July and noted the overgrown hedges that had been reported severely restricting the width of the footpath. Works will be instructed to clear these back in the autumn at the end of the bird nesting season.

Enquiry Refs – 22085929 / 22079903 / 11491497 (Action Required)

Westbury on Severn

EWS5 It was reported that the wooden stile on this Public Footpath on Ampney Lane was collapsing and unsafe. I inspected it and found the same issue, so contacted the landowner and agreed on the replacement of the stile with a new one. My contractor was tasked with the installation and this was completed on 16th July. See left photo below.

Enquiry Ref – 22075764 (Resolved)



EWS9 On 16th July cleared the wooden stile of overgrown hedgerow and brambles that had been obstructing it at the Ampney Lane end of this Public Footpath. My contractor also installed a new stile step to help walkers over the high stile that the landowner had previously installed – see photo to the right above.

EWS53 Checked the reported 'unsafe' handrail on the steps on this Public Footpath leading up the former railway bridge at Blaisdon village on 24th July. Found that three of the upright supports were rotten and tasked my contractor to replace these as soon as possible. This was completed on 29th July, and I can therefore close this as 'Enquiry Resolved'.
Enquiry Ref – 22081646 (Resolved)

EWS56 On 8th July I spoke with the farmer about this Public Footpath being blocked by a wheat crop. I was informed that it had now been removed from the field early and used for silage for the livestock. I however reminded them of the need to keep the footpath clear of the crop when they came to sow it next year.
Enquiry Ref – 22079656 (Resolved)

EWS78 / Severn Way West It was reported that a section of this Public Footpath which runs parallel to Goose Lane had become overgrown and almost impassable. My contractor was instructed to clear this and this was completed on 5th August.
Enquiry Ref – 22078323 (Resolved)



EWS92 Inspected this Public Footpath off Crowgate Lane on 19th August and met with the landowner. Discussed the issue of the blocked access at the stile with a high plank and overgrown hedgerow. The plank was immediately removed, and the hedgerow was cut back at the same time. It was promised that a new step would also be installed as soon as ground conditions improved.
Enquiry Ref – 22081049 (For Future Review)

EWS96 It was reported that a section of this Public Footpath which runs between Goose Lane had the riverbank had become too narrow from vegetation and an overgrown hedge. My contractor was instructed to clear this and this was completed on 5th August.
Enquiry Ref – 22078657 (Resolved)

EWS150 Inspected this Public Footpath on 19th August and with the help of my contractor the stile at the road end of the footpath was cleared of brambles that had been obstructing it. Also met with the son of the landowner and discussed the issue with the maize crop which was blocking the definitive line. I was shown a line which had been cleared through the crop closer to the site entrance, but this wasn't on the correct line. I reiterated where the line should have been cleared and will have further discussions with all those parties involved in this site.
Enquiry Ref – 60001618 (Action Required)

West Dean

RWD13 Inspected this Public Footpath on 17th July and found where it was blocked as reported with an out-of-date closure notice. I have notified our closures team who have contacted the landowner and requested them to respond to us regards these issues. Update – as of 9th September no response has been received, so they will be emailed again.
Enquiry Ref – 22082374 (For Future Review)

Woolaston

FWO81 My contractor installed a new wooden waymark post on the line of this public Footpath at Ashwell Grange on 2nd July. I also visited site later the same day, installed new waymark discs on the post as well as adjusting the pointers on the adjacent signpost outside the Ashwell Grange offices to reflect the recently diverted route.

FWO91 It was reported that a fallen tree was preventing access to this Public Footpath just off the A48 opposite the Sheepscombe campsite and when I inspected in June I found this to be the case. I therefore instructed my contractor to clear this and this was completed on 7 July.
Enquiry Ref – 22059542 (Resolved)

FWO100 New stickers installed on handrail to indicate direction of Public Footpath away from adjacent property.
Enquiry Ref – 22079454 (Resolved)

FWO102 It was reported that the steps on this Public Footpath next to the tea rooms on the A48 at Woolaston were buried with soil and other debris. I inspected the footpath on 9th July and found the issues as reported. My contractor was instructed to clear them and this was completed on 29th July.
Enquiry Ref – 22079456 (Resolved)

FWO115 It had previously been reported that this Restricted Byway was obstructed by flooding but that has now been resolved.
Enquiry Ref – 22059543 (Resolved)

New enquiries / issues received for July & August = 97

Enquiries Resolved for July & August = 93